

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES


Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):


- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.


**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**





HURST-SON DESIGN CO.
Sam Hurst
18812 Maple Ht Blvd.
Maple Ht Ohio 44137
(216) 475-8376
E-mail smhi29k@yahoo.com












HURST-SON DESIGN CO.
Sam Hurst
18812 Maple Ht Blvd.
Maple Ht Ohio 44137
(216) 475-8378
E-mail smht29k@yahoo.com








Glass Block Window w\ Retractable Screen




HURST-SON DESIGN CO.
Sam Hurst
18612 Maple Hts Blvd
Maple Hts, Ohio 44137
(216) 475-8376

Glass Block Window w\ fixed Screen Attachment




HURST-SON DESIGN CO.
Sam Hurst
18612 Maple Hts Blvd
Maple Hts, Ohio 44137
(216) 475-8376

"The Hide-Away Window System™"




HURST-SON DESIGN CO.
 Sam Hurst
 18612 Mapl Hts Blvd
 Maple Hts, Ohio 44137
 (216) 475-8376



It will be enclosed in
 walls.
 the
 building
 is
 covered / covered



HURST-SON DESIGN CO.
 Sam Hurst
 18612 Maple Hts Blvd
 Maple Hts, Ohio 44137
 (216) 475-8376




HURST-SON DESIGN CO.
Sam Hurst
18612 Maple Hts Blvd
Maple Hts, Ohio 44137
(216) 475-8376




HARRISON DESIGN CO.
 Sam Hurst
 18612 Maple Hts Blvd
 Maple Hts, Ohio 44137
 (216) 475-8376

① Operator
 Has
 The
 Bottom tier of
 the Glass block
 Section


② Operator
 Rolls Window
 Away From
 Assembly




③ The window
 Section Clear
 of Window
 Frame and
 Remaining Glassblock
 Window is pushed
 over




④b Vent is Attached
 To Glass block
 Section




⑤ Window with
 Attached Vent
 is forced back
 into its
 cavity




⑥




Window As it
 would appear
 from outside



HURST-SON DESIGN CO.
Sam Hurst
18612 Maple Hts Blvd
Maple Hts, Ohio 44137
(216) 475-8376



HURST-SON DESIGN CO.
Sam Hurst
18612 Maple Hts Blvd
Maple Hts, Ohio 44137
(216) 475-8376




HURST-SON DESIGN CO.
Sam Hurst
18612 Maple Hts Blvd
Maple Hts, Ohio 44137
(216) 475-8376




HURST-SON DESIGN CO.
Sam Hurst
18612 Maple Hts Blvd
Maple Hts, Ohio 44137
(216) 475-8376

To Be Used Where the Window Dimensions Constrain it used.




HURST-SON DESIGN CO.
Sam Hurst
18612 Maple Hts Blvd
Maple Hts, Ohio 44137
(216) 475-8376



↑ Offset track lowers
"11" Sub-Assembly is order to allow Glassblock Assembly the Ability to pivot without

Groove Cut Track




Slide cut into wall

Counterbalance Spring



Brake

HURST-SON DESIGN CO.
Sam Hurst
18612 Maple Hts Blvd
Maple Hts, Ohio 44137
(216) 475-8376




HURST-SON DESIGN CO.
Sam Hurst
18612 Mapl Hts Blvd
Maple Hts, Ohio 44137
(216) 475-8376



HADDLE



Disengage Locking Mechanism




motion




Roll HADDLE

DOWNWARD




HADDLE


HADDLE POLED BACK




HADDLE POLED BACK



Screen



HURST-SON DESIGN CO.
Sam Hurst
18612 Maple Hts Blvd
Maple Hts, Ohio 44137
(216) 475-8376



HURST-SON DESIGN CO.
Sam Hurst
18612 Maple Hts Blvd
Maple Hts, Ohio 44137
(216) 475-8376

